

I think that the 2,000ft. vertical separation rule should stay as it is above FL 290. I don't think 1,000ft. is enough time for a controller to successfully move to fast aircraft around if a problem in flight should occur.